



Mining
Technology

P O Box 91230
Auckland Park
Johannesburg 2006
South Africa
Tel. +27 11 358-0000
Fax. +27 11 726-5405
Internet: <http://miningtek.csir.co.za>

CONFIDENTIAL TO CLIENT

TITLE Mining of the 94 East faces, TauTona

CLIENT AngloGold. Mr. A Naismith

CONTACT Dr. Mike Roberts
0113580168
0824482301

DATE 19th December 2001

DISTRIBUTION Mr A Naismith, AngloGold
Mr SK Murphy, Tau Tona Mine
CSIR Division of Mining Technology

PREPARED BY Dr. S. M. Spottiswoode. PhD
Dr. M. K. C. Roberts. PhD (Eng)

CSIR REPORT NUMBER 2002-0035

CONDITIONS PERTAINING TO THE USE OF MINING TECHNOLOGY REPORTS

1. This report is the property of the sponsor and may be published by him provided that :
 - (a) The CSIR is acknowledged in the publication.
 - (b) It is published in full, or where only extracts therefrom or a summary or an abridgement thereof is published, the CSIR's prior written approval of the relevant extracts, summary or abridged report be obtained.
 - (c) The CSIR be indemnified against any claim for damages which may result from publication.
2. The CSIR will not publish this report or the detailed results without the sponsor's prior consent. However, the CSIR is entitled to use technical information obtained from this investigation but undertakes not to identify the sponsor or the subject of this investigation in doing so.
3. The sponsor will not make reference to the investigation or the report in any advertisement or promotional medium without the CSIR's written approval of the text of such advertisement or reference.
4. While care is taken to ensure the accuracy of any work performed by the CSIR under this Contract, the CSIR does not **guarantee or warrant the accuracy of the work or** the merchantability or commercial viability of the research results. Any claim for damages, whether direct or indirect, including consequential damages, against the CSIR **arising from this** Contract, shall be limited to an amount equal to the Contract Price or amount actually paid by the Client to the CSIR in respect of the work done in terms of this Contract, whichever is the smaller.

Introduction.

At the request of Mr Naismith, a CSIR team visited the 94E1 and 94E2 panels mining the Carbon Leader Reef in the north –east corner of Tau Tona shaft pillar on the 14th December 2001 to study the damage due to a rockburst and to recommend any steps that might reduce the potential for further rockburst damage.

The CSIR representatives were:

Dr. S.M. Spottiswoode.

Dr. M .K .C. Roberts.

The following persons from the mine accompanied them:

Mr. S. Murphy – Rock Mechanics Manager.

Mr. R. Saunders - Section Manager

Mr W Keefe – Acting Mine Overseer

Seismicity

A seismic event with $M=2.5$ occurred on the 4th December 2001 at 15:56 before the blast was due to go off. It located in front of the 94E1 and 94E2 panels about 88m in the footwall of the reef. The event caused substantial damage to these panels. The seismic details provided by the mine suggested that the source was close and parallel to the two advancing panels, with all the available evidence supporting this mechanism. The seismic data provided by the mine looked good, except that the event itself was not listed in the data file provided by the mine (“xevntqry.txt”).

1. The hypocentral location was close to the advancing faces.
2. Both possible fault planes of the moment tensor solution were nearly parallel to the overall face (longwall) direction
3. The given source dimension was almost as large as the longwall length
4. The damage was mostly in the face area and was similar along the entire face length

Description of damage as seen along the route of the visit

The visit travelled up a travelling way accessing the top strike gully to panel 94E1. We went down the face about 25 m until the face was blocked and then travelled along the 94E1 and 94E2 strike gullies and inspected the face areas near the ends of these gullies. Together with the abovementioned mine personnel, the following observations were made, introduced in order of initial observation, during this visit:

on the 94E2 (top) panel. A simple explanation is that, prior to the event, there was a more extensive region of fracturing ahead of the 94E2 panel. Closure in 94E2 was estimated as 200mm. In places some of the elongates had fallen out. Fall-outs of elongate support elements are not uncommon occurrences during rockbursts. The reasons for these fall-outs are complex and could result from one or more of the following, *inter alia*: FOG cantilevering over part or all of the support element; ride motion during the dynamic event; opening during the seismic event; squeezing out of elongates placed adjacent to backfill; poor installation. Many of these effects could be countered by the use of headboards and/or footboards.

History of strong ground motion.

Peak velocities were measured in 94E panels between November 2000 and August 2001 as part of SIMRAC project GAP709. 10 events produced strong ground motion in excess of 1 m/s during the 330 days of recording. Figure 2 shows the rate at which peak velocities were measured to have exceeded values ranging from 10 mm/s to 3 m/s. Although there was a sharp change in slope suggesting that the maximum PPV might be 3 m/s, the data alone cannot be used to exclude the possibility of exceeding 3 m/s at some stage.




Figure 2. Incidence of strong ground motion recorded by Peak Velocity Detectors in 94E, all data. From GAP709 final report (in preparation).

Suggested rockburst mechanism

The seismic event of the 4th December 2001 at 15:56 occurred on a structure sub-parallel to the face. As there was no known geological structure sub-parallel to the face, in accordance with good mining practice, the event created its own shear zone in previously competent rock as suggested above in the section on seismicity. Very high ground accelerations were needed for the type of footwall heave and bulking that was observed. As suggested McGarr (2001), higher stress drops and ground velocities are expected from failure of intact rock than from slip of previous (weak) geological features. This evidence points to mining induced slip of a structure ahead of and sub parallel to the stope faces. The fact that both faces were affected to a similar degree

also supports the assumption that the damage was caused by a mining-induced slip event in previously unfailed rock ahead of and sub parallel to the stope faces.

Geological features could well have been mobilised during the event (Murphy, 2001), but slip on them could not have resulted in the observed damage. Firstly, such slip would not have resulted in the extreme damage to the footwall and secondly, none of the features was close to parallel to the overall face direction. The report by Murphy (2001) provided a maximum estimated seismic moment of $4.0E9$, equivalent to $M=0.4$ by doing ESS studies on three faults in the area. This also supports the exclusion of previously identified faults as causing the event.

From the observed damage it was clear that the event caused rapid bulking of the footwall under high acceleration. In places, the remaining stope width was less than ± 70 cm. If persons were in the panels at the time of the event it could have resulted in injury or death.

The intense support at the face and the clamping effect of the backfill were very effective in limited the degree of hanging-wall fall-outs. A small reason for the damage to the footwall was that the footwall is not barred. The fundamental processes of the footwall rubbelsation are not understood.

Recommendations

The recommendations address two issues; the first is to reduce the possibility of such damage occurring again and the second is to lessen the chances of injury to persons due to dynamic footwall heave should an event occur again

1. **Stop the bottom panel, 94E1 and mine the top panel, 94E2, through to limit.**
The rationale behind this recommendation is that the overall face length will be reduced from the present 80 m (panels 94E1 and 94E2) to 30 m (94E2 only). Should a face-parallel slip occur in future it would affect a length of 30 m and not 80 m. This would result in a smaller event for similar distance of event from face and therefore lower accelerations thereby limiting the bulking of the footwall. There are also commonly recognised benefits of reduced face length in remnant conditions. The extraction of the bottom 94E1 panel can be considered later on the basis of the experience while mining 94E2. Decisions regarding whether and how to mine the bottom 94E1 panel will be based on analysis of the success, or otherwise, of the remaining panel 94E2.
2. **To improve alternate access to the top panel, a mid-panel escape way may be used.** We suggest that the advantages of the improved access and escape will exceed the disadvantage of softening the backfill. The small amount by which the top (93E2) panel currently lags the 94E1 panel should not necessitate any additional special precautions. The final abutment length created when 94E2 reaches its final planned limit will be less than the total current face length and therefore is not expected to result in any unusually large seismicity and the abutment itself.
3. **Increased the stoping width from the current 0.9 m to 1.3 m.** From the observed damage it was clear that the event caused rapid bulking of the footwall under high acceleration. In order to reduce this damaging effect on persons being projected onto the hanging wall, it is recommended that the stoping width be increased from the current 0.9 m to 1.3 m. This increase will not compromise the existing support system. The high closure rate should provide sufficient stress on the elongates even though they will be longer. . By providing more space between

the heads of the workers and the roof, the possibility of head and neck injuries will be reduced if rapid footwall heave does happen again.

Acknowledgements

We would like to thank Messrs, Murphy, Saunders and Keefe for their essential assistance during our brief visit to the site and for discussions afterwards.

References

Murphy, S.K. Assessment of the mining being in the North Eastern corner of the Carbon Leader Shaft Pillar Internal memorandum, TauTona Mine. 2001.

McGarr, A. Control of strong ground motion of mining-induced earthquakes by the strength of the seismogenic rock mass. Rockbursts and Seismicity in Mines – RaSiM5, SA Inst. Min. Metall., 2001.



Figure 3. Photograph taken in panel 94E1 looking down towards a person in the bottom strike gully. Note the rubble on the footwall derived from rubbelised footwall rocks. .



Figure 4. Photograph taken in the lower portion of panel 94E1 looking updip. The closure shown on the elongate showed that it performed well. Note again the rubble on the footwall rocks.

Dr. S.M. Spottiswoode.

Dr. M.K.C. Roberts.